

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8






Fig. 9



11 A

11.917



SP-8	SP-9	SP-10	SP-11	SP-12	SP-13	SP-14	SP-15	SP-16	SP-17	SP-18	SP-19	SP-20	SP-21	SP-22	SP-23	SP-24	SP-25	SP-26	SP-27	SP-28	SP-29	SP-30	SP-31	SP-32	SP-33	SP-34	SP-35	SP-36	SP-37	SP-38	SP-39	SP-40	SP-41	SP-42	SP-43	SP-44	SP-45	SP-46	SP-47	SP-48	SP-49	SP-50	SP-51	SP-52	SP-53	SP-54	SP-55	SP-56	SP-57	SP-58	SP-59	SP-60	SP-61	SP-62	SP-63	SP-64	SP-65	SP-66	SP-67	SP-68	SP-69	SP-70	SP-71	SP-72	SP-73	SP-74	SP-75	SP-76	SP-77	SP-78	SP-79	SP-80	SP-81	SP-82	SP-83	SP-84	SP-85	SP-86	SP-87	SP-88	SP-89	SP-90	SP-91	SP-92	SP-93	SP-94	SP-95	SP-96	SP-97	SP-98	SP-99	SP-100
Sporting Goods Co.										TSK																																																																																		
12-8-99																																																																																												
12 Field & Top Cavity Retainer Plates?																																																																																												
NET 2A																																																																																												

FIG. 13






FIG. 14



Wilson Sporting Goods Co.		7-10-00	TSK
Q mold (B tton CVavity Retainer Plate)			
BE Taa			

FIG. 15

